

## Supplementary Materials

Figure S1. DSC thermogram of polymer material recovered as by-product in EXP1.




Figure S2. X-ray diffraction patterns for polymer material recovered as by-product in EXP1.

